EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	696	(polypropylene propylene) and (strain near hardening)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/30 00:48
L2	2	(polypropylene propylene) with (strain near hardening) with (cable wire) with insulat\$5	US PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/30 00:49
L3	2	"03029345".pn.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/30 00:57
L4	0	"029345".pn.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/30 00:57
L5	4	"3029345".pn.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/30 00:57
L6	4	"2003029345".pn.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/30 00:58
L7	2	(polypropylene propylene) same (strain near hardening) same (cable wire) same insulat\$5	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/30 01:02

L8	81	(polypropylene propylene) and (strain near hardening) and (cable wire) and insulat\$5	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR		2008/03/30 01:03
L9	134	(polypropylene propylene) with (strain near hardening)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/30 01:05
L10	11	9 and (wire cable)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/30 01:05
L11	4	10 and insulat\$5	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/30 01:05
L12	203	(polypropylene propylene) same (strain near hardening)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/30 01:15
L13	20	12 and (wire cable)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/30 01:15
L14	7	13 and insulat\$5	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/30 01:15
L15	1	12 and ((ash chloride) near residue)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM TDB	OR	ON	2008/03/30 01:24

L16	3	10 and (melt near flow)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/30 01:40
S1	7	US-3968463-\$.DID. OR US-5047485-\$. DID. OR US- 6094337-\$.DID. OR US-6130385-\$.DID. OR US-6121335-\$. DID. OR US- 6599626-\$.DID. OR EP-0190889-\$.DID. OR EP-038491-\$. DID. OR EP-0885918- \$.DID. OR EP- 0961295-\$.DID. OR DE-1465640-\$.DID. OR	US PGPUB; USOCR; EPO; JPO; DERWENT	OR	OFF	2008/03/29 19:45
S2	5	S1 and (polypropylene propylene)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/29 21:24
S3	1	S2 and (strain near hardening)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/29 21:25
S4	0	S3 and (insulation dielectric)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/29 21:26
S 5	0	S3 and (cable wire)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/29 21:26
S 6	1	S3 and (blend mixture)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/29 21:27

S7	17	(fagrell-ola\$.in.)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/29 21:28
S8	4	S7 and (polypropylene propylene)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/29 21:28
S9	2	S8 and (strain near hardening)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/29 21:28
S10	2	S7 and (strain near hardening)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/29 21:39
S11	13	US-3968463-\$.DID. OR US-5047485-\$. DID. OR US- 6094337-\$.DID. OR US-6130385-\$.DID. OR US-6121335-\$. DID. OR US- 6599626-\$.DID. OR EP-0190889-\$.DID. OR EP-0384431-\$. DID. OR EP-0885918- \$.DID. OR EP-0885918- \$.DID. OR EP-	US-PGPUB; USPAT; USOAT; PPRS; EPO; JPO; DEFWENT; IBM_TDB	OR	ON	2008/03/29 21:40
S12	111	S11 and (polypropylene propylene)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/29 21:41
S13	2	S12 and (strain near hardening)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/29 21:41

S14	0	S13 and (cable wire)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OX	2008/03/29 21:41
S15	0	S13 and (insulation dielectric)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/29 21:42
S16	6	S11 not S1	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/29 21:42
S17	6	"190889".pn.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/29 21:43
S18	2	S17 and (strain near hardening)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/29 21:44
S19	0	S18 and (insulation dielectric)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/29 21:44
S20	0	S18 and (cable wire)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	SON	2008/03/29 21:45
S21	62	(nilsson-ulf\$.in.)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/29 21:50

S22	7	S21 and (polypropylene propylene)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/29 21:51
S23	2	S22 and (strain near hardening)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/29 21:51
\$24	42	"4365044".pn. "6130385".pn. "574801".pn. "574804".pn. "634454".pn. "142724".pn. "678527".pn. "688817".pn. "450342".pn.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	S. ON	2008/03/29 21:55
S25	15	S24 and (polypropylene propylene)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/29 21:55
S26	1	S25 and (strain near hardening)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/29 21:56
\$27	0	S26 and (insulation dielectric)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/29 21:57
S28	0	S26 and (cable wire)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/29 21:57

^{3/30/08 3:16:43} AM

C:\ Documents and Settings\ jgray\ My Documents\ EAST\ Workspaces\ 10538327.wsp